nexen.

AIR CHAMP® PRODUCTS

5H30 Repair Kit Supplement

NOTE: If the Drive Ring (Item 4) inside your 5H30 has three holes in its face, you must use the three regular Compression Springs (Item 7) included in this repair kit.

If the Drive Ring (Item 4) inside your 5H30 has nine holes in its face, you must use the nine red Compression Springs (Item 7) included in this repair kit.



Nexen Group, Inc. 560 Oak Grove Parkway Vadnais Heights, MN 55127 800.843.7445 Fax: 651.286.1099 www.nexengroup.com

ISO 9001 Certified